

The accupack is designed exclusively for dataloggers: **U0110M, U0141M, U0843M, U2422, U3120M, U3121M, U3430, U3631M, U4440, U4440M, U6841M, U7844M, U8410, U8410M**

WARNING - Replacement may only be carried out by a qualified service technician
- Read this procedure in detail before you replace it
- To add any additional information provided here, use manuals and other documents available in the *Downloads* section for a particular device at www.cometsystem.com

- Turn off the device:
 - press and hold down the lower button and release the button when the menu item bar lights up
 - briefly press the upper button
 - press the upper button briefly again to select **OFF**
 - press the lower button to turn off the device
- unscrew the rear of the device where the accu is located (use the TORX T10 screwdriver)
- disconnect the old accupack from the device
- connect the USB charger to the device, and **wait until the full battery symbol will be permanently lit** (see fig.)
- unpack the new A8205 accupack, check and, if necessary, adjust the position of the seal in the groove
- again check that the fully charged battery symbol is on the display and **then** connect the new accupack to the device *-! failure to observe this step can lead to the destruction of a new accupack !*
- assemble the device (the screws tighten gently)
- charge the unit fully (full-battery symbol must be **permanently lit**):
 - When charging, the device must be installed indoors with a maximum humidity of 85%, at an indoor temperature ranging between 0°C and +40°C.
- Turn device ON

